| Work Order ID 103709 June-27-13 10:06:15 AM | | | | | | *103 | 3709* | | · | | | | Page 1 |
|--|------------------------|--------------------|-----------------------|---|------------|----------------------|---------------------------|------------|--------------|---------------|-------------------|----------------------|----------------|
| Item ID: Revision ID: Item Name: | D3957-4 HINGE, DOOR | . RH LOW | /ER | | | Accept | *N900 | 040 | 100 |)* s | etup Star Stoj | ı | S1* S2* |
| Start Date: Required Date: Reference: | | Req'd Ç | ty: 1.00 Qty: 1.00 | | *1* *1* | | Cust Item II Customer: | | AR001 | | | | |
| Approvals: | Process Plan | | λ_ | Date:_ Date:_ | | Tooling: SPC (Y/N): | Da | te: te: | | R | un Stai Stoj | ր ՝՝ \] | R1* R2* |
| Sequence ID/ Work Center I | | Operation Descript | | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | | Set Up/ Run Hours | Tool ID | Tool # | Plan Code | Accept Qty | Reject Qty | Reject Number | Insp. Stamp |
| Draw Nbr | Revi | sion Nbr | | | | | | | | | | | |
| D3957 | Α | | | | | | | | | | | | |
| *100 *100* QC Quality Control | | | Memo INSPECT | RA111551 | | 0.00 TAS | 13/06/17 | | | | | | |
| 110 | | | | | | 0.00 | | | | | | | - 16 |
| *110* HandFinish Hand Finishing | | | Memo STRIP PA | ART | | 0.00 | | | | _/_ | THE, | 13.9 | <u> </u> |
| 120 *120* | | | | | | 0.00 | | | | 1 | b | HA | 3-7-6 |
| Powder Coating | | | Memo REPOW B | OER COAT P | ER QSI005 | 0.00 | | | | | 7 | | |

| Work Ord June-27-13 10: | | 03709 | | | Page 2 | | | | |
|--|---------------------------------|---|----------------------------------|-----------------------------|-----------------------------------|-------------|-------------|---------------|------------------------------|
| Item ID: Revision ID: Item Name: | D3957-4 HINGE, DO | OR RH LOWER | | Accept | *N90004010 | N * | Setup | Start Stop | 11/2 |
| Start Date: Required Date: Reference: | 6/25/13 : 6/26/13 RMA RA1 | Start Qty: 1.00 Req'd Qty: 1.00 | *1* *1* | | Cust Item ID: Customer: CU-DAR001 | | | | |
| Approvals: | Process P | lan: | Date: | Tooling: SPC (Y/N): | Date: | | Run | Start Stop | "NRT" |
| Sequence ID/ Work Center I 130 *130* QC Quality Control | D | Operation Description QC3- Inspect Part Finish Memo | | Set Up/ Run Hours 0.00 0.00 | Tool ID Tool # Plan Code | Acce Qty | pt Re Qt | • | Reject Insp. Number Stamp |
| *140 *140* Packaging Packaging | | | 5 TO79 Y USING NEW B/N | 0.00 | | | L | | M. W. 13-07-1 |
| *150 *150* QC Quality Control | | QC21- Final Inspection - Memo | Work Order Release | 0.00 | | | MCJ | | 3-07-17 MF |

13-09-16

| Tari | 1711.89 | | | | |
|----------------|---------|--|------------|---|------|
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| # - 2. A.A. | | | | | |
| | | | | | |
| | | | | • | |
| | | | | | 1 |
| | | | | | |
| | | | | | |
| | 1,5 | | . · | | |
| | 'e ' | | • | | |
| | | | | | |
| | | | | | 2 |
| | 1 | | | | |
| | Δ. | | | | |
| | | | | | |
| | | | | | ů, |
| | | | | | |
| | | | | • | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | 그는 전 그는 그렇게 꾸존하면 가면 하는데 그는 | | | |
| | | | | | |
| | | | | | |
| | | | | | 9.00 |
| | | | | | 1 |
| | | | | | |
| | | | | | |
| | | | | 1 | |
| | | | | | |
| | | | | 1 | |
| Fi | | - 1987年 - 19874 - 19874 - 19874 - 19874 - 19874 - 19874 - 19874 - 19874 - 19 | | | |
| * | • | | | · | |

June-27-13 10:06:15 AM

Work Order ID:

103709

Parent Item:

D3957-4

Parent Item Name:

HINGE, DOOR RH LOWER

Start Date: 6/25/13

Required Date: 6/26/13

Start Qty: 1.00

Required Qty: 1.00

Comments:

| Component Item ID/ Item Name | Replacement Item ID | Mfg/ Purch | Bin Item | Primary Location | Last Location | Route Seq ID | Unit of Measure | Qty on Hand | Qty per Kit | Total Qty | Qty Issued | Date Issued | Status |
|---------------------------------|------------------------|---------------|-------------|---------------------|------------------|-----------------|--------------------|----------------|-------------|--------------|----------------------------|----------------|--------------------------|
| D3957-4 | | Manufactured | No | | | | Each | 3.0000 | | 1 | | | |
| HINGE, DOOR RH LOW | ER | | | | | | | | e | av 20 99- | concernation of the second | | and the same of the same |

Location

Loc Qty

Loc Code

T NY

RA 111551 D3957-3/-4

Received @ Dart June 17th, 2013 Inspected@ Dart June 24th, 2013 CUSTOMER: PANORMA
CUSTOMER CONTACT: DONALD MANUEL
SHIPPED FROM:ALMA PQ, CANADA

Instructions for RA 111551 D3957-3/-4

- Return D3957-3 qty x1 needs to be striped and re powder coated
- Return D3957-4 qty x1 needs to be striped and re powder coated
- Both need separate work orders

Time Estimate = 1 HOUR ONLY (stores)

Departments Required: Stores (restocking)

Pictures Attached = NO

QTY INSPECTED = x1 D3957-3 B95525

x1 D3957-4 B95526

THIS INSTRUCTION SHEET MUST BE ATTACHED TO THE RESTOCKING WORK ORDER AT ALL TIMES!!!!

| DQA: | | | Date: | | <u></u> | | | | | | | | | | | | |
|---------------|------------------------|-----------|------------|------|---------------|---------------------------------------|----------|-----------------------------------|----------------------------|-----------|----------------------|-------------------|--------------|----------|--------------------|--|--|
| | | | | | | WORK ORDER NON | -C(| ONFO | RMANCE / L | JPDATE | | | | | A E R O S P A C E | | |
| QA Closed: | | | Date: | | | · · · · · · · · · · · · · · · · · · · | | | | | W | ork Order up | odate only | | | | |
| Work Order: | | | | | | DISPOSITION | | | AGAINST DEPARTMENT/PROCESS | | | | | | | | |
| | _ | | | | | Rework |] | | Skid-tube | Crosstube | | 1 | Water Jet | | Engineering | | |
| Part N | ۱o. | | | | | Scrap | 1 : | 1 | Machining | | Pro | d. Eng. Coor. | Quality | | | | |
| | | | | | | Use-as-is | 1 | Thern | noforming | Finishing | | 4 | re/Packaging | | Other | | |
| NCR N | No | | | | . | Suspected Unapproved | | | Large Fab | Composite | | | Supplier | | | | |
| Root | | | | | Desc | ription of work order update | | Initial | A | ction | | Sign & | | | | | |
| Cause | | Date | Step | Qty | | or non-conformance | Ch | nief Eng | Des | cription | | Date Verification | | | QC Inspector | | |
| Design | | | | | | | | | | | | | | | | | |
| Doc/Data | Щ | | | | | | | | | | | | | | | | |
| Equip/Tooling | | | | | | | | | | | | | | | | | |
| Handling/Pre | | | | | | | | | | | | | | | | | |
| Material | | | : | | | | | | | | | <u>.</u> | | | | | |
| Operator | Ш | | | | | | | | | | | | | | | | |
| Offset/Setup | Ш | | | | | | | | | | | | | | | | |
| Process | Ц | | | | | | | | | | | | | | | | |
| Supplier | | | | | | | | | | | | | | | | | |
| Training | | | | | | | | | | | | | | | | | |
| Transport | Щ | | | | | | | | | | | | | | | | |
| Unapproved | | | | | | | <u> </u> | | | | | | | | | | |
| | | | | | | | FA | ULT CAT | EGORY | | | | | | | | |
| Landii | | | | | | General | _ | 1 | | ı | | • | | | • | | |
| | - | Bending | | | | Bend | <u></u> | 4 | rogram | | <u> </u> | Outside Dim | ensions | | Pressure/Forced | | |
| | Centre Not Concentric | | | | | BOM/Route | | Grain | | | Over/Under tolerance | | | <u></u> | Set-up | | |
| | Cracks | | | | | Broken/Damage/Defect | | Hardware | | | | Part Incorred | ct . | <u></u> | Temperature/Cure | | |
| | Crimp/Kink/Ripple/Wave | | | | | Burrs | _ | Inspection Incomplete/Unqualified | | | | Part Lost/Missing | | | Weld | | |
| | Cuffs | | | | | Contamination | | • | ions Incomplete, | | | Part Moved | | <u> </u> | Wrong Stock Pulled | | |
| | Crushing | | | | ļ | Countersink | <u>_</u> | - 1 | ned/off center | - | L | Positioned V | Vrong | | • | | |
| | Heat Treat | | | | | Cut Too Short | <u> </u> | Mislabe | | | Power Loss/Surge | | | Other | | | |
| | $\overline{}$ | | n Strip in | Tube | | Drawing | <u></u> | Misread | 1 | | | | | | | | |
| | _ | /larks/Ch | | | ļ | Drill Holes | <u>_</u> | Off-set | | | | | | | | | |
| | _ | | equence | | <u> </u> | Finish | L | 4 | Calibration | | | | | | | | |
| | Wave/Twist in Tube | | | | | Fit/Function | 1 | lout of s | Sequence | | | | | | | | |



RETURN AUTHORIZATION

1270 Aberdeen Street Hawkesbury, Ontario K6A 1K7 27-May-13 DART RA Number: RA111551 Date: Customer Name: Panorama HPAN01 Customer Code: **DHS RA Number:** 418 668 3046 DHS PO#: PO4351 Telephone No: E-mail Address: dmanuelpanorama@bellnet.ca DART Invoice #: INV110652 **Donald Manuel** PAR13-232 Customer Ref: Contact Name: issued by: Lisa McMachen PAR/CAR/NCR/SQ: SQ10505 Part Number Description Quantity **Batch Number** Hinge, Door LH Lower D3957-3 B95525 D3957-4 Hinge, Door RH Lower B95526 Reason for Return: Originally ordered wrong part. Customer required part **Credit Instructions:** with helicoil installed. No charge D3957-043 & D3957-044 are being sent to customer on ☐ Full credit PAR13-232. None Commerical Invoice Yes 🔲 Include on Commerical Invoice: Return Instructions: Documentation (STC/ARC/ICA) Yes Part Number/Description / Value in USD Packing Slip Parts are aircraft parts / return to Manufacturer Prepaid _____ Collect YES Shipping Instructions: Courier FED-EX Account # DAS **RECEIVING RETURN AUTHORIZATION** Condition of Packaging: 600 Paperwork: P/L Receiver: Photograph Required Freight Company: PURO Date: RA NONE Yes **Quantity** Part Number Batch QC Verification CHG# W/O# Disposition QC Inspector AS Photograph Attached Condition: i)ate: Sealed Complete | Short H/W | Short Kit | No P/W | Damaged OC Comments Special Return/Rework Instructions: La From For Yes No Issue Credit: Invoice Amount: \$0.00 Restocking Fee: GM Approval: Freight: Net Credit:

Close Date:

Quality Assurance: